

[Federal Register Volume 82, Number 138 (Thursday, July 20, 2017)]

[Rules and Regulations]

[Pages 33439-33441]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2017-15031]

---

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. FAA-2017-0701; Directorate Identifier 2016-SW-063-AD; Amendment 39-18962; AD 2017-15-02]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Bell Helicopter Textron, Inc. (Bell) Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

---

**SUMMARY:** We are adopting a new airworthiness directive (AD) for Bell Model 212 and Model 412 helicopters. This AD requires replacing certain oil and fuel check valves and prohibits installing them on any helicopter. This AD is prompted by a report of cracked or leaking check valves. These actions are intended to address an unsafe condition on these helicopters.

**DATES:** This AD becomes effective August 4, 2017.

We must receive comments on this AD by September 18, 2017.

**ADDRESSES:** You may send comments by any of the following methods:

- Federal eRulemaking Docket: Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- Fax: 202-493-2251.
- Mail: Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.
- Hand Delivery: Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0701; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the economic evaluation, any comments received, and other information. The street address for the

Docket Operations Office (telephone 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this final rule, contact Bell Helicopter Textron, Inc., P.O. Box 482, Fort Worth, TX 76101; telephone (817) 280-3391; fax (817) 280-6466; or at <http://www.bellcustomer.com/files/>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

**FOR FURTHER INFORMATION CONTACT:** Jurgen E. Priester, Aviation Safety Engineer, Delegation Systems Certification Office, ASW-130, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5159; email [jurgen.e.priester@faa.gov](mailto:jurgen.e.priester@faa.gov).

## **SUPPLEMENTARY INFORMATION:**

### **Comments Invited**

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments prior to it becoming effective. However, we invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that resulted from adopting this AD. The most helpful comments reference a specific portion of the AD, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit them only one time. We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this rulemaking during the comment period. We will consider all the comments we receive and may conduct additional rulemaking based on those comments.

### **Discussion**

We are adopting a new AD for Bell Model 212 and Model 412 helicopters. This AD is prompted by a report that certain part numbered 209-062-520-001 check valves manufactured by Circor Aerospace as replacement parts have been found cracked or leaking on several Bell Model 427 and Model 429 helicopters. These check valves may be installed as engine oil check valves on Bell Model 212 helicopters. Similar check valves, part number 209-062-607-001, may be installed as fuel check valves on Bell Model 212 or 412 helicopters. These check valves may have a condition induced during assembly that can cause the valve body to crack, resulting in oil or fuel leakage. These suspect check valves are marked "Circle Seal" and were manufactured between October 2011 and March 2015. If not corrected, this condition could result in a crack, fuel or oil leakage, and subsequent failure of the engine or a fire and loss of control of the helicopter.

### **FAA's Determination**

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other helicopters of these same type designs.

### **Related Service Information**

We reviewed Bell Alert Service Bulletin (ASB) 212-15-153, dated September 4, 2015 (212-15-153), and Bell ASB 212-15-155, dated September 15, 2015 (212-15-155), for Model 212 helicopters

and Bell ASB 412-15-168, dated September 15, 2015 (412-15-168), for Model 412 helicopters. ASB 212-15-153 describes procedures for inspecting and replacing engine oil check valve part number (P/N) 209-062-520-001 installed on certain serial-numbered Model 212 helicopters. ASB 212-15-155 and ASB 412-15-168 describe procedures for inspecting and replacing fuel check valve P/N 209-062-607-001 installed on certain serial-numbered Model 212 and Model 412 helicopters.

## **AD Requirements**

This AD requires, within 25 hours time-in-service (TIS), replacing the engine oil and fuel check valves.

This AD also prohibits installing a check valve P/N 209-062-520-001 or P/N 209-062-607-001 that was manufactured by Circor Aerospace, marked “Circle Seal,” and marked with a manufacturing date code of “10/11” (October 2011) through “03/15” (March 2015) on any helicopter.

## **Differences Between This AD and the Service Information**

The manufacturer's service information describes procedures for an inspection of the check valves within 25 hours TIS for a crack and allows 300 hours TIS to determine if the valve is affected and to replace any affected check valve. This AD requires replacing all affected check valves within 25 hours TIS.

## **Costs of Compliance**

We estimate that this AD affects 161 (59 Model 212 and 102 Model 412) helicopters of U.S. Registry.

We estimate that operators may incur the following costs in order to comply with this AD. At an average labor rate of \$85, replacing each check valve (engine oil or fuel) will require about 1 work-hour, and required parts will cost \$85. For the Model 212, we estimate a total cost of \$340 per helicopter and \$20,060 for the U.S. fleet. For the Model 412, we estimate a total cost of \$170 per helicopter and \$17,340 for the U.S. fleet.

According to Bell's service information some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage by Bell. Accordingly, we have included all costs in our cost estimate.

## **FAA's Justification and Determination of the Effective Date**

Providing an opportunity for public comments prior to adopting these AD requirements would delay implementing the safety actions needed to correct this known unsafe condition. Therefore, we find that the risk to the flying public justifies waiving notice and comment prior to the adoption of this rule because the actions required by this AD must be accomplished within 25 hours TIS, a very short interval for helicopters used in firefighting and logging operations.

Since an unsafe condition exists that requires the immediate adoption of this AD, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in less than 30 days.

## **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## **Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

## **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

## **Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):



**2017-15-02 Bell Helicopter Textron, Inc. (Bell):** Amendment 39-18962; Docket No. FAA-2017-0701; Directorate Identifier 2016-SW-063-AD.

**(a) Applicability**

This AD applies to Bell Model 212 and 412 helicopters, certificated in any category, with an engine oil check valve part number (P/N) 209-062-520-001 or fuel check valve P/N 209-062-607-001 manufactured by Circor Aerospace, marked “Circle Seal” and with a manufacturing date code of “10/11” (October 2011) through “03/15” (March 2015), installed.

**(b) Unsafe Condition**

This AD defines the unsafe condition as a cracked or leaking check valve, which could result in loss of lubrication or fuel to the engine, failure of the engine or a fire, and subsequent loss of control of the helicopter.

**(c) Effective Date**

This AD becomes effective August 4, 2017.

**(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

- (1) Within 25 hours time-in-service:
  - (i) Replace each fuel check valve.
  - (ii) For Model 212 helicopters, replace each engine oil check valve.
- (2) After the effective date of this AD, do not install any check valve P/N 209-062-520-001 or P/N 209-062-607-001 manufactured by Circor Aerospace, marked “Circle Seal” and with a manufacturing date code of “10/11” (October 2011) through “03/15” (March 2015), on any helicopter.

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Delegation Systems Certification Office, FAA, may approve AMOCs for this AD. Send your proposal to: Jurgen E. Priester, Aviation Safety Engineer, Delegation Systems Certification Office, ASW-130, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5159; email [jurgen.e.priester@faa.gov](mailto:jurgen.e.priester@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector,

the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

Bell Alert Service Bulletin (ASB) 212-15-153, dated September 4, 2015; Bell ASB 212-15-155, dated September 15, 2015; and Bell ASB 412-15-168, dated September 15, 2015, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Bell Helicopter Textron, Inc., P.O. Box 482, Fort Worth, TX 76101; telephone (817) 280-3391; fax (817) 280-6466; or at <http://www.bellcustomer.com/files/>. You may review this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

**(h) Subject**

Joint Aircraft Service Component (JASC) Codes: 7900 Engine Oil System and 2800 Aircraft Fuel System.

Issued in Fort Worth, Texas, on July 7, 2017.

Scott A. Horn,  
Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.